



1. Download and unstuff “uploader_v1_40.sit”. You will obtain a folder named “uploader_v1_40”.
2. Open the “uploader_v1_40” folder and double click on “uploadergui.jar”. You should have the firmware utility, called Uploader, which looks like the following.



3. Turn on the FireWire enclosure and then plug it into the computer. The “Uploader” should be able to detect the bridge and display the current version of firmware as indicated by the red circle.



4. Click on “Upload/Upgrade Firmware” button and navigate to firmware version 3.8, which should be located at .../uploader_v1_40/data/FW911/fw20030721.bin.

When you have chosen “fw20030721.bin”, the Uploader will start updating your Oxford 911 bridge to run firmware version 3.8.

5. Click on the “Exit” button to quit the Uploader.

*Note: Users of FireWire bridge model “DT-0114” and “DT-0205” (CA-268F2 enclosure) can not update their Oxford firmware using Macintosh version of the Uploader. User of these bridges must use Windows version of the Uploader to update their bridges. Please see instruction for Windows version of the Uploader on how to run the update.